

# Inspection Photos

7/12/2017

Operator: PDC ENERGY INC - 69175

Location ID: 322906

Inspection Doc. Number: 682502412

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 322906



**Photo 1:** Photo taken from the southwest end of the battery location, facing northeast. Photo shows battery location appears to have been recently seeded, with straw used to stabilize the soil.



**Photo 2:** Photo taken from the southwest end of the battery location, facing east. Photo shows battery location appears to have been recently seeded, with straw used to stabilize the soil.



Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 322906



**Photo 3:** Photo taken from the southwest end of the well location, facing northeast. Photo shows well location appears to have been recently seeded, with straw used to stabilize the soil.



**Photo 4:** Photo taken from the south end of the battery location, facing south. Photo shows Canada thistle on the perimeter of the location. Weed management advised.