

Inspection Photos

7/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323371

Inspection Doc. Number: 682502414

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323371



Photo 1: Photo taken from the well location, facing south. Photo shows reclamation in process. Second growing season, if vegetation does not progress, additional seeding may be required.



Photo 2: Photo taken from the adjacent reference area. Photo shows vegetation over the reference.