

Inspection Photos

7/17/2017

Operator: PDC ENERGY INC - 69175

Location ID: 323307

Inspection Doc. Number: 682502451

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323307



Photo 1: Photo taken from the south end of the location, facing north. Photo shows all equipment has been removed from the location. Photo also shows that location does not appear to be progressing towards reclamation standards; location is predominantly undesirable weedy plant species, or exposed soil with no sign of desirable perennial vegetative establishment.



Photo 2: Photo taken from the north end of the location, facing south. Photo shows all equipment has been removed from the location. Photo also shows that location does not appear to be progressing towards reclamation standards; location is predominantly undesirable weedy plant species, or exposed soil with no sign of desirable perennial vegetative establishment.