

# Final Reclamation Inspection

July 17, 2017

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 335797

Adams County, CO

SESW Section 12 T1S R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: NORTH YORK  
Location ID: 335797



**Photo 1.** Photo taken from the northeast location, facing West. Surface roughening was performed around the location perimeter.



**Photo 2.** Photo taken from the northeast location, facing South. Surface roughening was performed around the location perimeter.

Inspection Photos  
Location Name: NORTH YORK  
Location ID: 335797



**Photo 3.** Photo taken from the western location, facing South. Surface roughening was performed around the location perimeter.



**Photo 4.** Photo taken from the southern location, facing East. Surface roughening was performed around the location perimeter.