

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2017

Submitted Date:

07/10/2017

Document Number:

680200074**FIELD INSPECTION FORM**
 Loc ID 440634 Inspector Name: KELLERBY, SHAUN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|---------------------------------|
| Knudson, Dwayne | (970) 456-3335 | dknudson@ursaresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 440637 | WELL | DG | 02/22/2017 | LO | 045-22709 | B&V 41A-13-07-96 | WK |
| 441598 | WELL | WO | 02/22/2017 | LO | 045-22845 | B&V 11B-18-07-95 | WK |

General Comment:[Inspection conducted in response to Complaint Doc# 200443093.](#)

Inspected FacilitiesFacility ID: 440637 Type: WELL API Number: 045-22709 Status: DG Insp. Status: WK**Complaint**

Comment: Active Hydraulic Stimulation operation at the time of inspection. Cal Frac on Site, 045-22709 and 045-22845 were undergoing treatments. Operator reported that 6 wells were producing, and 4 wells were flowing through flow back equipment. Green completions equipment was staged on site. No odors were observed at the time of inspection. Staff used a portable gas meter to spot check several locations around the B&V pad. No indications of methane were found during inspection,

Corrective Action:

Date:

Facility ID: 441598 Type: WELL API Number: 045-22845 Status: WO Insp. Status: WK**Complaint**

Comment: Active Hydraulic Stimulation operation at the time of inspection. Cal Frac on Site, 045-22709 and 045-22845 were undergoing treatments. Operator reported that 6 wells were producing, and 4 wells were flowing through flow back equipment. Green completions equipment was staged on site. No odors were observed at the time of inspection. Staff used a portable gas meter to spot check several locations around the B&V pad. No indications of methane were found during inspection,

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401336817 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4193872 |