

Flowline and Final Reclamation Inspection

July 17, 2017

Operator: NOBLE ENERGY INC - 100322

API: 05-123-11782

Weld County, CO

SWSE Section 33 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DAVIS #2-33
API: 05-123-11782



Photo 1. Photo taken 8/23/2016 from the entrance of the location, facing East. Previous inspection documented that large portions have no native, perennial vegetative growth and that weedy, annual plants were the majority of the vegetative growth.



Photo 2. Photo taken from the eastern location, facing West. Appears the location is in the same vegetative condition, approximately one year later. Bare ground with little to no perennial vegetative growth that is reflective of reference areas.

Inspection Photos
Location Name: DAVIS #2-33
API: 05-123-11782



Photo 3. Photo taken from the southern location, facing West. Appears the location is in the same vegetative condition, approximately one year later. Bare ground with little to no perennial vegetative growth that is reflective of reference areas. List B CO Noxious weed, Musk thistle, observed flowering at the location.



Photo 4. Reference photo taken north of the location, illustrating native, perennial vegetative growth.