

Flowline and Final Reclamation Inspection

July 17, 2017

Operator: NOBLE ENERGY INC - 100322

API: 05-123-18601

Weld County, CO

NWSW Section 29 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TOLLGATE FARMS #29-12G6
API: 05-123-18601



Photo 1. Photo taken from the approximate well location, facing East. Well location appears to be reflective of vegetative reference levels.



Photo 2. Reference photo taken south location, facing South.

Inspection Photos
Location Name: TOLLGATE FARMS #29-12G6
API: 05-123-18601



Photo 3. Photo taken from the battery location, facing West. Disturbance evident due to bare ground, gravel remains and weedy, annual vegetation not reflective of reference crop vegetative levels. The battery location has not been reclaimed per Rule 1004.



Photo 4. Photo taken from the battery location, facing West along the access road. The access road has not been reclaimed per Rule 1004.