

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/18/2017

Submitted Date:

07/18/2017

Document Number:

679902779**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
305007 _____ Welsh, Brian _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 86610Name of Operator: CAERUS WASHCO LLCAddress: 1001 17TH STREET - STE #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Grant, Rachael	918-585-1650 ext 212	regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277584	WELL	PR	11/30/2005	GW	125-09253	WELP 13-24	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and water tank		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 0		
Comment:	Removed from unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber. Not in use		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.867130,-102.257030	

Comment: Fiberglass water tank 50% buried

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity) 210bbbs

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities									
Facility ID:	277584	Type:	WELL	API Number:	125-09253	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Welp 11-24, 12-24, 13-24, 14-24) 1340' N @ 39.87093/-102.25729								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass					

Comment: Erosion on access needs maintenance

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT