

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/12/2017

Submitted Date:

07/19/2017

Document Number:

666803368**FIELD INSPECTION FORM**

Loc ID 324098 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257028	WELL	PR	04/07/2000	GW	045-07509	BERNKLAU RMV 161-33	PR

**General Comment:**[Facilities on location ID 259575](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:					Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:									
Corrective Action:								Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS		
CONDENSATE		0					,		
Comment:									
Corrective Action:								Date:	

**Paint**

Condition

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	257028	Type:	WELL	API Number:	045-07509	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
Seeding	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT