



photo 1: Facing east toward the location.



photo 2: There is storage of supplies at the location.



photo 3: Facing south toward the reclaimed slope.



photo 4: The wattles along the slope have filled in with sediment and there are noxious weeds (Canada thistle) along the south slope.