

Inspection Photos
Location Name: Schmerge 34-4
API: 05-123-23145



1) West of wellhead looking east



2) West of wellhead looking east

Inspection Photos
Location Name: Schmerge 34-4
API: 05-123-23145



3) East of wellhead looking west



4) North of tank looking south

Inspection Photos
Location Name: Schmerge 34-4
API: 05-123-23145



5) North of tank looking south



6) West of battery looking east

Inspection Photos
Location Name: Schmerge 34-4
API: 05-123-23145



7) Erosion southeast entrance of battery looking south



8) Erosion southeast entrance of battery looking west

Inspection Photos
Location Name: Schmerge 34-4
API: 05-123-23145



9) Erosion southeast entrance to battery



10) North discharge points