

July 20, 2017 COGCC Environmental Field Inspection of DIVERSIFIED ENERGY LLC (Diversified) J.P  
Weise #1 Location ID: 312773.



Location sign.



Location. Recent grading.



Location.



Pit with animal tracks.



Tank battery with berm and vegetation (weeds).



Load out valve locked and oil staining covered with material.





Oil staining.



Oil staining covered with material.



Oil staining covered with material.