

July 20, 2017 COGCC Environmental Field Inspection of ARCH OIL AND GAS (Arch) J.P Weise #2
Location ID: 312774.



Location sign.



Pump Jack and well head.



Gas venting from 1 1/2-inch line. Valve in open position.



Land treatment area. Vegetation (weeds) present.



Land treatment area. Evidence of livestock.