

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jul 20, 2017 12:21:24 PM MDT
Server Receive Date:	Jul 20, 2017 12:31:30 PM MDT
Reference Number:	20170720-1863522604
Location:	339-351 High Flume Loop, Durango, CO 81303, USA Jul 20, 2017 12:21:23 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Jul 20, 2017
Well Name	JACQUEZ, THOMAS GAS UNIT A 2
API Number	50670849600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

