

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jul 20, 2017 2:37:45 PM MDT
Server Receive Date:	Jul 20, 2017 2:38:04 PM MDT
Reference Number:	20170720-1863531406
Location:	338-350 High Flume Loop, Durango, CO 81303, USA Jul 20, 2017 2:37:47 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Jul 20, 2017
Well Name	JACQUEZ, THOMAS GAS UNIT A 1
API Number	50670746300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Weed Debris

Picture North to South



Picture East to West



Picture West to East

