



View east along access road toward pit.



View east at access road and former produced water pit #117501.





View south across pit, mud cracks and puddled water indicate subsidence and lack of crop growth.



View west across pit showing lack of crop growth and low, muddy areas.