

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2017

Submitted Date:

07/25/2017

Document Number:

666803397**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 335359      Murray, Richard      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER      State: CO      Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257648	WELL	PR	10/13/2004	GW	045-07583	KELL 35-3	PR
257649	WELL	PR	04/12/2001	GW	045-07584	GMU 26-14 (C35)	PR
257660	WELL	PR	10/13/2004	GW	045-07585	BENZEL 35-7 (C35)	PR
257665	WELL	PR	10/13/2004	GW	045-07589	KELL 35-6 (C35)	PR
273777	WELL	PR	03/05/2005	GW	045-10283	CRAIG 35-6A (C35)	PR
273779	WELL	PR	03/04/2005	GW	045-10284	CRAIG 35-5A (C35)	PR
274937	WELL	PR	03/22/2005	GW	045-13440	GMU 35-4A1(C35)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment: Use BMPs for weed around wellheads and location

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 4

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 3

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents

#

Capacity

Type

Tank ID

SE GPS

METHANOL

1

1000 GAL

STEEL AST

Comment: Centralized battery

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type

Capacity

Permeability (Wall)

Permeability (Base)

Maintenance

Comment:

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	500 BBLs	STEEL AST		39.488356,-107.745318	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	257648	Type:	WELL	API Number:	045-07583	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	257649	Type:	WELL	API Number:	045-07584	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	257660	Type:	WELL	API Number:	045-07585	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	257665	Type:	WELL	API Number:	045-07589	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	273777	Type:	WELL	API Number:	045-10283	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	273779	Type:	WELL	API Number:	045-10284	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	274937	Type:	WELL	API Number:	045-13440	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Ditches	Pass					
Sediment Traps	Pass					
		Culverts	Pass			
Berms	Pass					
		Sediment Traps	Pass			
		Ditches	Pass			
		Gravel	Pass			
		Check Dams	Pass			
Seeding	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT