

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2017

Submitted Date:

07/25/2017

Document Number:

666803403**FIELD INSPECTION FORM**
 Loc ID 311608 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266194	WELL	PR	11/08/2003	GW	045-09125	SCHAEFFER 12-6C (F12W)	PR
266197	WELL	PR	10/01/2013	GW	045-09128	SCHAEFFER 12-6B (F12W)	TA
276406	WELL	PR	01/20/2006	GW	045-10454	SHAEFFER 12-3A (F12W)	PR
276407	WELL	PR	02/06/2006	GW	045-10453	SHAEFFER 12-12A (F12W)	PR

General Comment:Shared tank battery with location ID 334680

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

1

Comment: Chemical unit at separator

Corrective Action:

Date:

Type: Plunger Lift

7

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

6

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS			
CONDENSATE		1	500 BBLS	STEEL AST			39.462544,-107.726912			
Comment:										

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 266194 Type: WELL API Number: 045-09125 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 266197 Type: WELL API Number: 045-09128 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Current form 4 on file to continue to Temporarily Abandoned well

Corrective Action:

Date: _____

Facility ID: 276406 Type: WELL API Number: 045-10454 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 276407 Type: WELL API Number: 045-10453 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Gravel	Pass			
		Culverts	Pass			
Ditches	Pass					
Seeding	Pass					
Gravel	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT