

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2017

Submitted Date:

07/25/2017

Document Number:

666803404**FIELD INSPECTION FORM**

Loc ID 334680 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266227	WELL	PR	09/18/2003	GW	045-09133	SHAEFFER 11-1A (D12B)	TA
266228	WELL	PR	11/10/2003	GW	045-09132	SHAEFFER 12-4C (D12B)	PR
266229	WELL	PR	09/15/2014	GW	045-09131	SHAEFFER 12-4A (D-12B)	PR

**General Comment:**

Tank battery on locationID 334603

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

# 3

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 2

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 266227 Type: WELL API Number: 045-09133 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Current form 4 on file to continue to Temporarily Abandoned well

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 266228 Type: WELL API Number: 045-09132 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 266229 Type: WELL API Number: 045-09131 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
		Culverts	Pass			
Rip Rap	Pass					
Seeding	Pass					
Ditches	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT