

Inspected Facilities

Facility ID: 425667 Type: LAND API Number: - Status: CL Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Application	Adequate		
Comment	No cuttings piles or liquid observed onsite. Site has been seeded and mulched. Remediation #9294 remains open pending additional soil sample results.			
Corrective Action				Date: _____

Spill/Remediation:

Comment:

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____