

Inspection Photos
Location Nessua 4
API:05-123-08810



Riser at pump jack is this line hot or where does it go



unused equipment beam compressor and chemical pot



Inspection Photos
Location Grant Properties #3
API:05-001-07649



Stained soil inside berms at tank



Wellhead sign and stained soil

Inspection Photos
Location Grant Properties #3
API:05-001-07649



Unused equipment



Stained soil from leaking gear box

Inspection Photos
Location Grant Properties #3
API:05-001-07649



Stained soil at motor mounts



Unused equipment

Inspection Photos
Location Grant Properties #3
API:05-001-07649



Unused equipment



Stained soil inside doghouse, trash