

Inspection Photos

7/27/2017

Operator: PETRO-CANADA RESOURCES (USA) INC -
72085

Location ID: 311680

Inspection Doc. Number: 675103761

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 1: Photo taken from the northwest corner of the location, facing southeast. Photo shows erosion on cut bank. Photo shows location has not been re-contoured per CA's



Photo 2: Photo taken from the west end of the location, facing southeast. Photo shows erosion on cut bank. Photo shows location has not been re-contoured per CA's

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 3: Photo taken from the southwest corner of the location, facing northwest. Photo shows erosion on cut bank. Photo shows location has not been re-contoured per CA's



Photo 4: Photo taken from access road southeast of the location, facing north. Photo shows access road had not been re-contoured or re-graded as required per CA's. Hat (indicated by yellow arrow) used for reference. Red line indicates width of road.



Photo 5: Photo taken from access road southeast of the location, facing north. Photo shows access road had not been re-contoured or re-graded as required per CA's.