

# Inspection Photos

7/27/2017

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 319767

Inspection Doc. Number: 675103769

Adams County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 319767



**Photo 1:** Photo taken from the south end of the well location, facing northwest. Photo shows well and equipment has been removed. Location still appears to require compaction alleviation, re-contouring, re-grading and re-vegetating.



**Photo 2:** Photo taken from the south end of the well location, facing north. Photo shows well and equipment has been removed. Location still appears to require compaction alleviation, re-contouring, re-grading and re-vegetating.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 319767



**Photo 3:** Photo taken from the south end of the well location, facing northeast. Photo shows well and equipment has been removed. Location still appears to require compaction alleviation, re-contouring, re-grading and re-vegetating.



**Photo 4:** Photo taken well location facing south. Photo shows area of the down slope portion of the well location where erosion is evident. This should be repaired during the re-contouring of the location.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 319767



**Photo 5:** Photo taken from the northeast end of the well location, facing north. Photo shows location still appears to require re-contouring and re-grading.



**Photo 6:** Photo taken from the access road on the northwest end of the well location. Photo shows access road still requires compaction alleviation, re-contouring, re-grading and re-vegetating

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 319767



**Photo 7:** Photo taken from southwest corner of the battery location. Photo shows facilities have been removed. Location appears to still require compaction alleviation and revegetation.



**Photo 8:** Photo taken from the battery location. Photo shows Canada thistle has established in the battery location. This is a Colorado State listed noxious weed and needs to be managed and removed.