

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2017

Submitted Date:

07/31/2017

Document Number:

666803415**FIELD INSPECTION FORM**

Loc ID 335163 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278820	WELL	PR	02/19/2009	GW	045-10952	GMU 23-14 (C26NW)	PR
278821	WELL	PR	06/08/2005	GW	045-10951	GMU 23-14C(26NW)	PR
278822	WELL	PR	02/19/2009	GW	045-10950	GMU 26-4A	PR
278823	WELL	PR	09/09/2010	GW	045-10949	GMU 26-4D(C26NW)	PR
278824	WELL	PR	02/15/2009	GW	045-10948	GMU 26-5A (C26NW)	PR
279429	WELL	PR	02/06/2009	GW	045-11031	LAZIER 23-15C (C26NW)	PR
279430	WELL	PR	02/11/2009	GW	045-11030	LAZIER 23-15B(C26NW)	PR
295380	WELL	PR	02/01/2011	GW	045-15737	LAZIER 26-2C (C26NW)	PR
296345	WELL	PR	02/13/2009	GW	045-15995	GMU 23-13C (C26NW)	PR

General Comment:[Shared tank battery with location ID 383338](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 9		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		39.504043,-107.744854
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent	Adequate	
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLs	STEEL AST		39.503985,-107.744742	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent	Adequate	
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	278820	Type:	WELL	API Number:	045-10952	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	278821	Type:	WELL	API Number:	045-10951	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	278822	Type:	WELL	API Number:	045-10950	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	278823	Type:	WELL	API Number:	045-10949	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	278824	Type:	WELL	API Number:	045-10948	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	279429	Type:	WELL	API Number:	045-11031	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	279430	Type:	WELL	API Number:	045-11030	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	295380	Type:	WELL	API Number:	045-15737	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			

Comment: **Plunger Lift**

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES