

Form Information

| | |
|----------------------|---|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Reclamation Tablet (reclamationtablet) |
| Submission Date: | Jul 21, 2017 10:19:25 AM MDT |
| Server Receive Date: | Jul 21, 2017 10:19:32 AM MDT |
| Reference Number: | 20170721-1863571494 |
| Location: | 580 High Flume Loop, Durango, CO 81303 Jul 21, 2017 10:18:49 AM MDT [View Map] |

Information

| | |
|------------------------|------------------------------|
| Name | reclamationtablet |
| Date | Jul 21, 2017 |
| Well Name | JACQUEZ, THOMAS GAS UNIT B 1 |
| Location Name (Other) | sw team |
| API Number | 50670746400 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Other |
| Picture North to South | |



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

Sprayed Russian knapweed and musk thistle NE of pad in reclamation area

Notes

questionable if the weeds are in the interim reclamation or in adjacent rangeland. approximately 150ft from pad