

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2017

Submitted Date:

07/31/2017

Document Number:

687900205**FIELD INSPECTION FORM**

Loc ID 333350 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757 #110City: HOUSTON State: TX Zip: 77227-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Giussani, Albert	806-894-0200/806-638-1296	albert_giussani@oxy.com	Engineering Advisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211798	WELL	PR	05/23/1985	GW	055-06033	SHEEP MOUNTAIN UNIT 9-26	PR
211845	WELL	AL	06/07/1983	LO	055-06082	SHEEP MOUNTAIN UNIT 1-26-L	AL
211846	WELL	AL	06/07/1983	LO	055-06083	SHEEP MOUNTAIN UNIT 2-26-O	AL
211860	WELL	PR	04/09/1984	GW	055-06098	SHEEP MOUNTAIN UNIT 2-35-C	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Wellhead and plumbing		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 211798 Type: WELL API Number: 055-06033 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 211845 Type: WELL API Number: 055-06082 Status: AL Insp. Status: ALFacility ID: 211846 Type: WELL API Number: 055-06083 Status: AL Insp. Status: ALFacility ID: 211860 Type: WELL API Number: 055-06098 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
There are 2 wells 100' E. to 200' SE of compressor station.	duranj	07/31/2017