

Inspection Photos
Location Name: Northglenn State
Location #425699



WELL HEAD TAKEN FROM THE SOUTH



TANK BATTERY AND SEPARATOR taken from the NW

Inspection Photos
Location Name: Northglenn State
Location #425699



STAINED SOIL IN TANK BATTERY



TANK BATTERY STAINED SOIL

Inspection Photos
Location Name: Northglenn State
Location #425699



STAINED SOIL AT WELLHEAD



STAINED SOIL AT WELLHEAD

Inspection Photos
Location Name: Northglenn State
Location #425699



STAINED SOIL AT WELLHEAD



STAINED SOIL AT WELLHEAD

Inspection Photos
Location Name: Northglenn State
Location #425699



ECD BY PASSED FROM TANKS SHUT IN VALVE IN OPEN POSITION



STAINED SOIL AT WELLHEAD

Inspection Photos
Location Name: Northglenn State
Location #425699



ECD BY PASSED FROM TANKS SHUT IN VALVE IN OPEN POSITION



PIN IN SHUT IN VALVE