

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2017

Submitted Date:

08/01/2017

Document Number:

666803429**FIELD INSPECTION FORM**

Loc ID 311612 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269872	WELL	PR	07/02/2012	GW	045-09416	LAST DANCE 12-2	PR
287362	WELL	PR		GW	045-12984	LAST DANCE 13B-2-792	PR
287577	WELL	PR		GW	045-12999	LAST DANCE 13D-2-792	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 3

Comment:

Corrective Action:

Date:

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 3

Comment: [Chemical units, 2 at wellhead, 1 at pig](#)

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 3

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment: <a href="#">At pig station</a>					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity) 500gal

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	6	200 BBLs	STEEL AST		39.474322,-107.639047		
Comment:							
Corrective Action:							Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	YES	
Comment:	Bradenhead valve open	
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 269872 Type: WELL API Number: 045-09416 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 287362 Type: WELL API Number: 045-12984 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 287577 Type: WELL API Number: 045-12999 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Seeding	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			
Gravel	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT