

Inspection Photos

7/31/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327002

Inspection Doc. Number: 675103780

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327002



Photo 1: Photo taken from the south end of the location, facing northeast. Photo shows pipe riser and trash debris remaining on the location.



Photo 2: Photo taken from the south end of the location, facing west. Photo shows pipe riser and trash debris remaining on the location.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327002



Photo 3: Photo taken from the south end of the location. Photo shows Canada thistle on location. This is a Colorado State listed noxious weed and needs to be removed.



Photo 4: Photo taken from the location, facing west. Photo shows revegetation in process over the reclamation area.