

Inspection Photos
Location Name: Rockwell #1
API: 05-123-11690



Stained soil



Unmarked 1" steel riser at wellhead

Inspection Photos
Location Name: Rockwell #1
API: 05-123-11690



Unmarked 2" steel risers at separator



Crude oil tank berm

Inspection Photos
Location Name: Rockwell #1
API: 05-123-11690



Crude oil tank berm



2' steel midstream riser

Inspection Photos
Location Name: Rockwell #1
API: 05-123-11690



Produced water vault placarding



Production facility