

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/01/2017

Document Number:

666803435**FIELD INSPECTION FORM**

Loc ID 324422 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291922	WELL	PR	12/06/2007	GW	045-14548	FEDERAL 11-13A(RM11)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

1

Comment: Process piping from wellheads to separators

Corrective Action: 5 days to mark and tag unused line(s) and 10 days to Contact the Engineering Integrity department to discuss flowline testing requirements per Rule 1102.

Date: 08/08/2017

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.449214,-107.860058
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Insufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: 291922	Type: WELL	API Number: 045-14548	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gradient Terraces	Pass			
		Culverts	Pass			
		Rip Rap	Pass			
Gravel	Pass					
Sediment Traps	Pass					
		Culverts	Pass			
Rip Rap	Pass					
Berms	Pass					
Ditches	Pass					
		Sediment Traps	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT