

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2017

Submitted Date:

07/26/2017

Document Number:

680401705

FIELD INSPECTION FORM

Loc ID 324471 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 922 EAST 2ND AVENUE
City: DURANGO State: CO Zip: 81301

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
,	970-385-0696	inspections@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275738	WELL	PR	02/14/2012	GW	051-06059	FEDERAL 11-90-35#1	SI

General Comment:

[MIT to maintain SI/TA status.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLs	STEEL AST		39.058706,-107.413358

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 275738 Type: WELL API Number: 051-06059 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: MIT to maintain SI/TA status.
Pressured casing to 555 psi. Hold for 15 min. Final pressure 546 psi. -9 psi loss. OK
Test witnessed by COGCC using gauges on wellhead.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401353999	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207689