

Inspection Photos

7/31/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 326980

Inspection Doc. Number: 675103786

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326980



Photo 1: Photo taken from the location, facing north. Photo shows pipe equipment remaining on the location



Photo 2: Photo taken from the northwest end of the location, facing southeast. Photo shows the disturbance area. This location has an active, ongoing remediation project. See project #9344 for additional details



Photo 3: Photo taken from the south end of the location, facing north. Photo shows the location remains predominantly exposed soil. Upon closure of remediation project #9344, reclamation activities will need to be performed.



Photo 4: Photo taken from the location. Photo shows the reclamation area remains predominantly exposed soil. Upon closure of remediation project #9344, reclamation activities will need to be performed.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326980



Photo 5: Photo taken from the access road, west of the location, facing east. Access road will need to be reclaimed upon closure of remediation project #9344.



Photo 6: Photo taken from the access road, west of the location, facing east. Photo shows erosion evident throughout the sloped areas of the access road leading to the location.