

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2017

Submitted Date:

08/02/2017

Document Number:

678300791

FIELD INSPECTION FORM

Loc ID 302803 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

General Comment:

[inspection of tank battery facility. associated wells not inspected at same time](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment: earthen berm			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:						Date:

Paint						
Condition						
Other (Content)						
Other (Capacity)	60 bbl					
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent		Adequate		
Comment:						
Corrective Action:						Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent		Adequate		
Comment:						
Corrective Action:						Date:

Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:

Flaring:						
Type						
Comment:						
Corrective Action:						Date: