

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/28/2017

Submitted Date:

07/31/2017

Document Number:

666803418**FIELD INSPECTION FORM**

Loc ID 334666	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				Findings: <u>13</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285781	WELL	PR	01/06/2007	GW	045-12515	JUNIPER 1-13A (M1E)	PR
285875	WELL	PR	12/27/2006	GW	045-12582	JUNIPER 2-16A (M1E)	PR
285876	WELL	PR	12/30/2006	GW	045-12581	JUNIPER 2-16 (M1E)	PR
285877	WELL	PR	12/19/2006	GW	045-12580	JUNIPER 1-13 (M1E)	PR
296480	WELL	PR	10/23/2008	GW	045-16049	JUNIPER 1-12A (M1E)	PR
296481	WELL	PR	10/09/2008	GW	045-16050	JUNIPER 2-9(M1E)	PR
296482	WELL	PR	10/19/2008	GW	045-16051	JUNIPER 1-12(M1E)	PR
296483	WELL	PR	10/21/2008	GW	045-16052	JUNIPER 12-4A(M1E)	PR
296484	WELL	PR	10/30/2008	GW	045-16053	JUNIPER 11-1A (M1E)	PR
296609	WELL	PR	10/19/2008	GW	045-16088	JUNIPER 2-9A (M1E)	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

10

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Flow Line

10

Comment: [Process piping from wellhead to separators](#)Corrective Action: [5 days to mark and tag unused line\(s\) and 10 days to Contact the Engineering Integrity department to discuss flowline testing requirements per Rule 1102.](#)Date: 08/05/2017

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

10

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,

Comment: [In same berm as 3-500bbls tanks](#)

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity) 500gal

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	<100 BBLS	Open Top		39.472130,-107.623050		
Comment:		At wellhead, hooked up to well API # 05-045-12515 Bradenhead					
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	300 BBLS	STEEL AST		39.471964,-107.622655		
Comment:							
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	3	500 BBLS	STEEL AST		39.472167,-107.622712		
Comment:							
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285781	Type:	WELL	API Number:	045-12515	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift, Bradenhead hooked up to flat tank								
Corrective Action:						Date:			
Facility ID:	285875	Type:	WELL	API Number:	045-12582	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285876	Type:	WELL	API Number:	045-12581	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285877	Type:	WELL	API Number:	045-12580	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296480	Type:	WELL	API Number:	045-16049	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296481	Type:	WELL	API Number:	045-16050	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296482	Type:	WELL	API Number:	045-16051	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296483	Type:	WELL	API Number:	045-16052	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	296484	Type:	WELL	API Number:	045-16053	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	296609	Type:	WELL	API Number:	045-16088	Status:	PR	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: _____

Comment: [Last posted production numbers May 2017](#)

Corrective Action:

Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
Seeding	Pass					
		Culverts	Pass			
Sediment Traps	Pass					
Berms	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401358839	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4211757
666803419	NT0 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4211748
666803420	NT0 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4211749
666803421	NT0 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4211750