



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the southeastern corner of the well pad facing northward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*), intermediate wheatgrass (*Thinopyron intermedium*), and western wheatgrass (*Pascopyrum smithii*).



Photo 3: View of the southern portion of the project area from the northeastern corner facing westward. Approximately 200 musk thistles are growing within the interim reclamation areas and need to be controlled



Photo 4: View of the western portion of the project area from the southwestern corner facing northward.