

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/11/2017

Submitted Date:

08/07/2017

Document Number:

679100122

FIELD INSPECTION FORM

Loc ID 423374 Inspector Name: KUBECZKO, DAVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 100 WAUGH DR SUITE 400
City: HOUSTON State: TX Zip: 77007

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Eric Sanford		esanford@sginterests.com	

General Comment:

Date of Inspection: 5-11-17
Type of Inspection: Construction, Containment, Stormwater
Location Name: McIntyre Tanks 1 & 2 Pad
Location ID #: 423374
Form 2A#: 401133514
API #: NA
Preliminary stormwater and containment BMPs for this tank pad access road and site clearing and grubbing is being conducted; most of the access road has been in place with borrow ditches and rock check dams in-place; heavy earthwork and cuts and fills are planned for later in the summer season.