

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Battery sign at tanks, no current operator or emergency contact information



Stained soil around load line bucket on southwest tank. Top of load line bucket is not in place, standing fluid inside with no wildlife protection

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



South side of tank battery looking north. Actively growing weeds inside and around tanks. Southwest tank does not have contents/capacity labeled



South side of tanks looking North. Actively growing weeds

Inspection Photos

Location Name: Moonshine 36-11-65

API: 05-123-31800



East side of tanks, actively growing weeds



Animal burrow in northeast side of tank berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Water tank missing capacity, NFPA label. Production water written on tank but hard to read.



Southwest oil tank missing contents/capacity label



Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Trash in heater treater shed



1-1" unused/unmarked riser north side of heater treater shed
2-2" unused/unmarked risers north side of heater treater shed

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



2-2" unused/unmarked risers north side of heater treater shed



3-2" Risers plumbed in to each other north side of heater treater

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Unused meter run set with no meter



North side of battery looking south

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Unused rod north side of pump jack shed



Actively growing weeds at pump jack

Inspection Photos

Location Name: Moonshine 36-11-65

API: 05-123-31800



Stained soil inside of pump jack shed



Trash on south side of pump jack shed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Pump jack looking east, open top container containing fluid with no wildlife protection. Stained soil around wellhead



Pump jack looking west from tanks

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Propane tank with no labeling , south side



Propane tank with no labeling, north side