

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/09/2017

Document Number:

674901858

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Brown, Walt	970-385-1372	wabrown@fs.fed.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448730	SPILL OR RELEASE	CL	02/03/2017		-	SPILL/RELEASE POINT	EI

General Comment:

On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP REM #10004 project area (Facility ID #448730). For the most recent field inspection report for this facility, please refer to document #674901407. Forest Service representatives Walt Brown and Lou Sovocool were present during this inspection. BP representatives Andy Hawk and Steve Moskal were also present during this site visit.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					Forest Service approved seed mix.
Waddles	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP REM #10004 project area (Facility ID #448730). For the most recent field inspection report for this facility, please refer to document #674901407. Forest Service representatives Walt Brown and Lou Sovocool were present during this inspection. BP representatives Andy Hawk and Steve Moskal were also present during this site visit. The area along Saul's Creek that was protected with truck mats during the initial clean-up phase was inspected during this site visit. The link to a photograph of this area is attached to this inspection report. The area near the release point has been reseeded with Forest Service approved seed mix. Vegetation monitoring will reoccur in the fall of 2017 and spring of 2018, along with follow up soil sampling. Analytical results will be provided by the operator via a supplemental Form 27.	hughesj	08/09/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901859	Area where truck mats were used during initial action.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221478
674901860	Reseeded area near release point.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221479
674901861	REM #10004 project area, looking downstream.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221480