

# Inspection Photos

8/9/2017

Operator: FORESTAR GROUP INC - 21180

Location ID: 395653

Inspection Doc. Number: 675103808

Morgan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FORESTAR GROUP INC - 21180  
Location ID: 395653



**Photo 1:** Photo taken from the north end of the location, facing southeast.



**Photo 2:** Photo taken from the north end of the location, facing south. Photo shows reclamation area of the location.

Inspection Photos  
Operator: FORESTAR GROUP INC - 21180  
Location ID: 395653



**Photo 3:** Photo taken from the north end of the location, facing west.



**Photo 4:** Photo taken from the center of the location. Photo shows areas where remediation and reclamation efforts had been conducted. Evidence of a previous seeding remains (straw from crimping). Very little desirable perennial vegetative grown/germination/establishment evident. Plants seen here predominantly annual sunflower or undesirable weedy plant species. Additional remediation/reclamation efforts may be required.



**Photo 5:** Photo taken from the center of the location. Photo shows vegetation over the reclamation area. Evidence of a previous seeding remains (straw from crimping). Very little desirable perennial vegetative grown/germination/establishment evident. Plants seen here predominantly annual sunflower or undesirable weedy plant species. Additional remediation/reclamation efforts may be required.