

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2017

Submitted Date:

08/04/2017

Document Number:

679100105**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☒  
KUBECZKO, DAVE 2A Doc Num: 401269141**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Linda Callahan		lcallahan@swbell.net	
Dave Kubeczko		dave.kubeczko@state.co.us	

**General Comment:**

Date of Inspection: 06-28-17

Type of Inspection: Form 2A Pre-Permit Approval Onsite

Location Name: East Combustor Facility

Form 2A # 401269141

Location ID #: NA

API #: NA

Conducted onsite for proposed combustor pad location (approximately 30' by 30') with operator on 06-28-17; location will have a gravel pad, combustor, liquids knock-out tank, and flowlines; location is near existing gathering line so minimal disturbance for hookup will be needed; location is rangeland and abandoned well location and will not require interim reclamation since the combustor will operate for the lifetime of the oil and gas wells in this field; location should be inspected once constructed, flowline tested, and in operation.

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401366531	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217974">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217974</a>