



view to NE from access road to Hopper 10-15A location
no sheens observed on water and no odor of hydrocarbons noted
by environmental staff person
WCR 20.5 running diagonally from upper left to upper right of
image parallel to fence line

8.8.2017 09:14