

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2017

Submitted Date:

08/11/2017

Document Number:

680401763**FIELD INSPECTION FORM**Loc ID 313455 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10343Name of Operator: QEP ENERGY COMPANYAddress: 1050 17TH STREET - SUITE 800City: DENVER State: CO Zip: 80265**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Maez, Leonard		leonard.maez@qepres.com	All inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224030	WELL	IJ	03/04/2014	DSPW	083-06087	MCCLEAN BASIN 2	SI

General Comment:[Routine UIC Inspection.](#)

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action	L		Date:
Type	Access		
comment:			
Corrective Action	L		Date:

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			
		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Filters		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Pump inside housing		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV STEEL		37.465469,-108.927991
Comment:					
Corrective Action:					
		Date:			

Paint

Condition Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLS	STEEL AST		37.465479,-108.927783
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 224030 Type: WELL API Number: 083-06087 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 400 Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) Inj Zone: DSCR

TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 08/16/2012

Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC Inspection. Well shut in for repairs. Waiting on rig.Corrective Action: Reschedule MIT well after repairs complete. Date: 08/16/2017Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT