

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/11/2017

Submitted Date:

08/07/2017

Document Number:

679100122**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 423374 KUBECZKO, DAVE 2A Doc Num: _____

Operator Information:OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Eric Sanford		esanford@sginterests.com	

General Comment:Date of Inspection: 5-11-17Type of Inspection: Construction, Containment, StormwaterLocation Name: McIntyre Tanks 1 & 2 PadLocation ID #: 423374Form 2A# 401133514API #: NA

Preliminary stormwater and containment BMPs for this tank pad access road and site clearing and grubbing is being conducted; most of the access road has been in place with borrow ditches and rock check dams in-place; heavy earthwork and cuts and fills are planned for later in the summer season.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401367892	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4219104