

Stormwater Inspection

August 11, 2017

Operator: RENEGADE OIL & GAS COMPANY LLC- #74165

Location ID: 319860

Adams County, CO

NWNW Section 20 T2S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 1. Photo taken of the tank battery sign at location.



Photo 2. Photo taken from the entrance of the tank battery location, facing South. Stormwater erosion evident as an erosion channel funnels around the northern battery location and continues off location into the adjacent cropland.

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 3. Photo of the tank battery location, facing Southwest. Appears an unused tank is being stored at location and needs to be removed within 90 days of this inspection.



Photo 4. Photo taken from the eastern tank battery location, facing West. Gully erosion forming at location that is contributing to sediment discharge off location.

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 5. Photo taken from the western tank battery location, facing East. Gully erosion forming at location this is contributing to sediment discharge off location.



Photo 6. Photo taken from the western tank battery location, facing West. Photo taken from the point of discharge.