

Inspection Photos  
Location WAILES 2  
API:05-001-08152



**WELL SIGN AND PUMP JACK**



**WELLHEAD CHEMICAL POT AND HIGH PRESSURE DUCT TAPE AND RAGS**