

# Inspection Photos

8/14/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP  
- 47120

Location ID: 302889

Inspection Doc. Number: 675103833  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120  
Location ID:302889



**Photo 1:** Photo taken from the southwest corner of the tank battery location, facing northeast. Photo shows tank battery location appears to have been seeded, then crimped with straw to stabilize the soil.



**Photo 2:** Photo taken from the southwest corner of the tank battery location, facing east. Photo shows meter shed equipment still remains on location.