

Inspection Photos

8/14/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 317730

Inspection Doc. Number: 675103836

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID:317730



Photo 1: Photo taken from the location, facing northeast. Photo shows meter shed equipment remains on location. This all equipment needs to be removed in accordance to reclamation rule 1004.a