

Inspection Photos

8/14/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 327317

Inspection Doc. Number: 675103838
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID:327317



Photo 1: Photo taken from the location, facing east. Photo shows pipe remaining on location. Inspection doc. #682502088 required operator to removed equipment.



Photo 2: Photo taken from the southwest corner of the location, facing east. Photo shows the battery and well location have had additional reclamation work conducted per CA's from Inspection doc. #682502088

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID:327317



Photo 3: Photo taken from the southwest corner of the location, facing north. Photo shows the battery and well location have had additional reclamation work conducted per CA's from Inspection doc. #682502088



Photo 4: Photo taken from the access road, facing west. Photo shows access road has not been reclaimed per CA's from inspection doc. #682502088

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID:327317



Photo 5: Photo taken from the access road, facing west. Photo shows access road has not been reclaimed per CA's from inspection doc. #682502088



Photo 6: Photo taken from the access road, facing east. Photo shows cattle guard, access road and gate have not been reclaimed per CA's from inspection doc. #682502088