



**photo 1:** Facing southeast toward the location. A fence remains around the location.



**photo 2:** Facing south at the location. There are tall undesirable weeds throughout the location (Horseweed, Kochia sp.).



**photo 3:** Center of the location facing northwest. There is predominately undesirable vegetation throughout the location.



**photo 4:** Facing toward the east side of the location.



**photo 5:** Center of the location facing east. A shovel and 100 foot tape measure shows the extent of undesirable vegetation.



**photo 6:** Facing west at the surrounding undisturbed reference area.